



apeks

SERVICE BULLETIN

Product : ATX/ XTX Regulators

SER NO: 701 0001 – 807 0001

Date : 26TH June 2008

Dear Customer,

It has come to our attention that ATX / XTX regulators produced between January 2007 and June 2008 could have a potentially serious defect.

The problem is related to the 2nd stage assembly of any XTX/ ATX regulator, including any XTX / ATX Stage 3 set and octopus which fall within the range of serial numbers 701 0001 and 807 0001.

It has come to our attention that the diaphragm cover (see diagram) may have been missed during the assembly of the 2nd stage and under certain conditions, this could allow the diaphragm to become displaced. This can be visually inspected through the front cover, but ideally the front cover should be removed to ensure the diaphragm cover is in place.

To enable us to provide you with a better service please report your findings together with the regulator serial numbers to the following email address info@apeks.co.uk

This is a worldwide recall. Apeks apologises for any inconvenience this recall might cause, but thank you in advance for your support in this matter. We are dedicated to making the world's best diving products and to ensure diver safety at all costs; this solution seems the only reasonable course of action.

Please contact the technical department if you need any assistance or have any further query.



Apeks Marine Ltd. Neptune Way, Blackburn, Lancs. BB1 2BT.

TEL :0044 (0) 1254 692200

FAX : 0044 (0) 1254 692211

email-info@apeks.co.uk